

项目编号：LA2023-M-24

鄂尔多斯市乌兰煤炭（集团）有限责任公司  
道路沉陷修复工程项目

安全现状评价报告

法 人 代 表：王普贤

技 术 负 责 人：王 莉








评价项目负责人：姚振明

内蒙古隆安安全评价有限公司

二零二三年十一月



## 评价人员

	姓名	资格证书号	从业登记编号	专业	签字
项目负责人	姚振明	S011011000110201000169	010639	采矿	
项目组成员	苗风有	0800000000100907	004147	采矿	
	郑锐	1800000000300084	033191	采矿	
	姬长兴	1700000000300202	030739	安全	
	侯宗有	S011011000110203000065	040453	地质	
	王国辉	1700000000200143	017991	机械	
	杨彦鸿	0800000000203638	009296	矿建	
	杨瑞华	0800000000207457	008992	电气	
报告编制人	姚振明	S011011000110201000169	010639	采矿	
	郑锐	1800000000300084	033191	采矿	
	侯宗有	S011011000110203000065	040453	地质	
报告审核人	贾在忠	0800000000100908	004149	机电	
	刘凤	1800000000200881	020638	地质	
过程控制 负责人	李焘	1800000000300099	033188	安全	
技术负责人	王莉	0800000000100890	005284	电气	